T20, R15, Sec.26 W–25

T20, R15, Sec.34 W–19

T20, R15, Sec.36 W–29

T19, R15, Sec.2 W–23

T20 R15

Sec 35

TR 464 (60' R/W)

TR 465 (60' R/W)

TR 466 (60' R/W)

TR 470 (60' R/W)

TR 470 (R/W unknown)

SR 179

Robert A. McIntire
OR.58–278 9/8/2000
OR.58–280 9/8/2000
5.0 ac p.8–54
2800078000

David M. Cicconetti
Kathleen J. Cicconetti
OR.243–848 4/25/2013
25.0 ac
2800049000

Vincent H. Cicconetti
OR.187–1186 3/16/2006
29.982 ac p.19–653
2800059000

James D. and Cynthia A. Brady
227–133 5/10/1985
1.349 ac p.10–404
2800791000

James D. and Cynthia A. Brady
258–78 3/4/1993
1.478 ac p.14–159
2800790001

Judd L. and Laura G. Shearer
OR.216–1712 2/12/2010
20.0 ac total p.14–420
Sec 26 = 0.987 ac
Sec 35 = 19.013 ac
2800792000

Donald P. and Pamela S. Troyer
267–306 1/17/1995 p.14–708
13.632 ac total
Sec 26 = 10.941 ac
Sec 35 = 2.691 ac
2800055000

The Ohio Fuel Gas Company
127–157 9/11/1952
Columbia Gas Transmission Corp as per auditor's records
21.8 ac
2890015000

Pamela S. Parks
Donald P. Troyer
253–507 11/19/1991
16.37 ac total
Sec 26 = 11.18 ac
Sec 35 = 5.19 ac
p.6–59
2800131000

Jeffrey A. McMillen
OR.162–690 8/29/2003
2.5 ac total p.16–833
Sec 35 = 1.235 ac
Sec 35 = 1.262 ac
2800133001

Joan D. Kirk
OR.237–3277 9/20/2012
1.33 ac p.7–813
2800130000

Donald P. and Pamela S. Troyer
OR.218–167 5/6/2010
6.449 ac total p.16–796
Sec 26 = 0.026 ac
Sec 35 = 6.423 ac
2800133000

Elaine D. and Robert A. Burgett
OR.208–1844 1/8/2009
6.53 ac p.14–75
2800223001

Robert A. and Elaine D. Burgett
OR.136–515 1/24/2003
OR.136–517 1/24/2003
OR.146–387 4/23/2003
116.252 ac p.18–504
2800084000

Floyd Deward Jr. and Patricia J. Spreng
OR.136–507 1/24/2003
OR.136–511 1/24/2003
OR.158–848 7/31/2003
64.848 ac
2800223000

Jeffrey R. Burgett
OR.193–1291 12/1/2006
2.622 ac p.19–877
2800223002

Robert A. and Elaine D. Burgett
OR.136–515 1/24/2003
OR.136–517 1/24/2003
OR.146–387 4/23/2003
13.30 ac
2800084000

Marvin F. and Betsy A. Edwards
OR.186–2519 2/14/2006
4.5 ac
2800083001

Marvin F. and Betsy A. Edwards
OR.186–2519 2/14/2006
2.4613 ac
2800083002

Thomas L. and Susan A. Rochelle
OR.163–589 9/8/2003
1.2287 ac p.12–139
2800083000

Beth A. and Nicholas C. Doering
OR.193–1128 11/29/2006
5.9307 ac p.19–874
2800121003

Thomas L. and Susan A. Rochelle
OR.200–2237 10/30/2007
46.372 ac p.2–452
2800121000

Jeremy L. and Rachel A. Burgett
OR.94–742 11/30/2001
OR.215–671 12/4/2009
5.071 ac p.18–137
2800087000

Reinhilde E. Brooks
180–988 7/31/1972
OR.192–2822 11/2/2006
⃠ 5.0 ac
2800035000

Camille A. Reusser
260–281 6/11/1990
D. OR.174–3448 9/3/2004
1.447 ac p.14–230
2800135001

David L. and Nancy J. Kick
OR.200–2240 10/30/2007
65.439 ac p.2–452
2800120002

Richard W. and Mary Ann Sprang
203–96 8/18/1978
253–189 10/21/1991
254–749 3/5/1992
48.553 ac
2800157000

Mary Louise Kick
OR.200–2243 10/30/2007
2.325 ac p.2–452
2800120000

Ronald G. and Tricia A. Kick
OR.200–2235 10/30/2007
61.419 ac p.2–452
2800121004

Thomas L. and Susan A. Rochelle
OR.200–2237 10/30/2007
9.365 ac p.2–452
2800120001

Fred H. Wolf
OR.201–2456 12/27/2007
OR.201–2458 12/27/2007
OR.201–2460 12/27/2007
OR.201–2462 12/27/2007
OR.213–319 8/25/2009
⃠ 11.17 ac
2800215000

Cheryl K. Wolf
277–651 4/3/1997
OR.201–2462 12/27/2007
OR.213–317 8/25/2009
10.805 ac p.15–121
2800124000

David L. and Nancy J. Kick
OR.200–2240 10/30/2007
4.481 ac p.2–452
2800121001

David L. and Nancy J. Kick
262–216 11/9/1993
13.82 ac
2800247000

David L. and Nancy J. Kick
262–216 11/9/1993
8.8385 ac
2800749000

David L. and Nancy J. Kick
219–436 1/28/1983
12.3415 ac p.10–95
2800748000

0' 200' 400' 600'

1" = 200'

LET IT BE KNOWN, THIS MAP HAS BEEN PREPARED AS A REFERENCE GUIDE TO PROPERTY OWNERSHIP. WE BELIEVE THIS INFORMATION TO BE CORRECT AND CURRENT, HOWEVER IT IS NOT INTENDED FOR ANY LEGAL USE, WHETHER IT BE IN SALES, TRANSFERS, TRADES, LEASES OF ANY TYPE, ETC., AND DO NOT ACCEPT RESPONSIBILITY FOR ERRORS OF ANY NATURE OR OMISSIONS CONTAINED HEREIN.

⃠ new survey required for next transfer

Last Revision: 4/25/2013

T-20, R-15, Sec. 35
Washington Twp.
Holmes County, Ohio

W-24