


Joseph P. & Carolyn L. Cross Vol. 248 Pg. 930

Roy R. Weaver
Vol. 244
Pg. 731
P.B. 12
Pg. 293

I. Pin F'd N.E. corner South 1/2
Frac'l Sec. 11, T9N
R7W, S.E. corner N1°38'32" E,
1,117.77'
Lot 44, 1st Qtt. P.B. 10 Pg. 952
T9N, R7W of Hardy
Twp, Hol. Co., Ohio

Calculated Line
558°32'08" E 196.10'
± 30' Private Drive

59.29'
N58°31'00" W



59.50'
I. Pinset
N48°05'00" E 359.50'
300.00'

Previous Plat,
P.B. 4 Pg. 154
gives 1.68 Ac.

The purpose of this
survey was to reestablish
Line AB.

This resurvey yields
1.647 acres.

Richard D. & Eloise S.
Croskey
Vol. 243 Pg. 653

Lee N. & Alma R. Keyse
Vol. 264 Pg. 857

15.71'
I. Pin F'd
399.69'
415.40'


Bruce E. & Pamela L.
Martin
Vol. 249 Pg. 108

A 541°59'00" E 182.80'

I. Pinset

Bird feeder post
foundation is on corner.

David H. & Terri L.
Brillhart Vol. 228 Pg. 23



Known as part of S.E. 1/4 of
Frac'l Sec. 11, T9N, R7W of
Har. Twp., Hol. Co., Ohio

Robert L. Kasner P.S. 5193
P.E. 28820
8/3/94

