



I.P.(S) in middle of new ditch
 I.P.(F) bent badly new one set near N.E. crnr of wall.

Approximate to U.S. R. 62 E. S. R. 83
 N 25° 03' E 300'

Lands of Robert E. & Hazel M. Barker.

N 08° 17' E

The tie to the S.W. crnr of the N.E. 1/4 S 22, T 9 N, R 7 W was not run, only the lines shown hereon. See V205 P546 & PB 5 P34



Known as part of the N.E. 1/4 S 22, T 9 N, R 7 W of Hardy Twp., Hol. Co., Ohio.

Robert L. Kasnar P.S. 5193
 P.E. 28820
 8/31/81

MAP OFFICE COPY