

NE corner Sec 25
Washington Twp.

99' offset SR-5-342

NW corner Sec 30
Ripley Twp.

Ripley Township (RP-05)
Section 30 T-18 R-14



2300411000 pt Sec 30 **A** George K. Read
Speedy Read
232-450 9/2/1986
OR 201-3253 1/9/2008
0.002 ac.

2300756000 pt Lot 105 **B** George K. Read
Speedy Read
232-450 9/2/1986
OR 201-3253 1/9/2008
0.002 ac.

2300760000 pt Lot 111 **C** Ronald D. Manchester Jr.
277-614 3/31/1997

2300951000 pt Sec 30 **D** Robert J. Bricker
OR 203-1633 3/26/2008
0.007 ac p.19-1248

2380000000 pt OL 1 **E** Robert J. Bricker
OR 203-1633 3/26/2008
0.013 ac p.19-1248

2300952001 pt OL 6 **F** Bernard and Janet Lewis
OR 183-1697 9/23/2005
0.025 ac p.19-506

2360002001 pt OL 2 **G** LLMK, Ltd.
OR 168-3029 12/16/2003
0.019 ac p.2-358

2360074000 pt OL 4 **H** LLMK, Ltd.
OR 188-928 4/24/2006
0.005 ac SFT

2300761000 pt OL 4 **I** James Murray and Beatrice Kathryn Smith
216-531 3/18/1982
229-252 11/1/1985
229-254 11/1/1985
0.01 ac SFT

2300754001 **J** George K. and Stacy J. Read
Wpt Lot 103
232-450 9/2/1986
OR 201-3253 1/9/2008
OR 215-893 12/8/2009
0.006 ac. p.19-1608


Lakeland Beach Subdivision
Original plat signed by Commissioners 3/5/1923
Revised by CJ 14, Page 234 on 6/9/1923
Recorded Plat Book 1, Pages 379-380 10/24/1923

Replat of Outlot 3
Plat Book 19-745 Platted 6/28/2006
Lots 332 thru 337

**Replat of Part of Outlots 1 & 6
And Lots 17-28 & Lots 32-39**
Plat Book 2-440 Platted 1-19-2007
Lots 338 thru 345

Pauline Greenough Allotment No. 1
Plat 15-111 Platted 11/20/1996

S.F.T. new survey required
for next transfer



LET IT BE KNOWN, THIS MAP HAS BEEN PREPARED AS A REFERENCE
GUIDE TO PROPERTY OWNERSHIP. WE BELIEVE THIS INFORMATION TO
BE CORRECT AND CURRENT. HOWEVER IT IS NOT INTENDED FOR ANY
LEGAL USE, WHETHER IT BE IN SALES, TRANSFERS, TRAVELS, LEASES
OF ANY TYPE, ETC., AND DO NOT ACCEPT RESPONSIBILITY FOR
ERRORS OF ANY NATURE OR OMISSIONS CONTAINED HEREIN.

Last Revision: 12/2/2010

**Lakeland Beach Subdivision
and
NW part Section 30, T-18, R-14
Ripley Twp.
Holmes County, Ohio**

RP-05C