

pg 620.00

I.P. Set 20.00' I.P. Set
Duncan Heirs P.B. 1 Pg. 125
No Recent Vol. & Page.
587°39'00"E 90.00'

Gail E. & Zona Faye Patterson,
Wayne Robert & Judith Faye Kinsey

See Note: 0.0682 Ac.
Vol. 235 Pg. 703 Lots 5/50
110.00'

23.00'
27.00'
27.00'
45.00'

Drill hole fd
in sidewalk

N3°00'00"E

WATER STREET 33'

NORTH

William
Lautenslager I.P. Fd 2
Vol. 35
Pg. 210



N3°00'00"E


22.00' 22.00'
587°39'00"E 88.00'
Lots 5/50

0.091 Ac.
Jeffrey N. & Teresa L. Caring
Vol. 248 Pg. 538
P.B. 12 Pg 511

I.P. Fd 2

22.00' NB7°39'00" W 88.00'

I.P. Fd 110.00' 10' Alley Drill hole in Sidewalk



GRAPHIC SCALE IN FEET

LOT 5 of Duncan's Addition to
The Village of Oxford (now Killbuck)
dated 11/10/1870, S.W. 1/4 Sec. 6, T8N,
R7W, Village of Killbuck,
Killbuck Twp., Hol. Co., Ohio.
said Lot 5 is now Lot 50 in the
Village of Killbuck.

Robert L. Kasner P.S. 5193
190156 P.E. 28820
9/25/94

Note: This a corrective survey of the "North Half"
of Lot 5, Vol. 38 Pg. 210 carried the correct size for
Lot 5, 72' N/S by 110' E/W. The very next transfer
Vol. 40 Pg. 102 carried an incorrect size for Lot 5,
90' N/S by 110' E/W. This error led to the "South Half"
45' N/S by 88' E/W being sold off.

NOV 1 4 1994
Recorded NOV 1 5 1994
Plat Vol. 14
Deed vol 266 pg 668

AT 1:33 o'clock pm
Holmes Co. Ohio Fee: \$20.00
Pg. 650 Recorder: Sally Mullen
PLAT APPROVED
9/19/94

VOL. 14 PAGE 650