

Village of Killbuck
Bucy Subdivision
Lot 3

(Plat Vol.2 Page 62)

Killbuck Township
S.W. Qtr. Sec. 6
T-8 N; R-7 W
Holmes County, Ohio


SURVEYED FOR: Will Morehouse

REFERENCES:

Deeds as shown

Plat Vol. 3 Page 88B
Plat Vol. 3 Page 62B
Plat Vol. 2 Page 62
Plat Vol. 4 Page 164
Plat Vol. 4 Page 107
Plat Vol. 5 Page 165
Plat Vol. 5 Page 10
Plat Vol. 7 Page 393
Plat Vol. 12 Page 969
Plat Vol. 19 Page 2683
Plat Vol. 19 Page2346
unrecorded survey by Donald C. Baker dated
Aug 11, 2026.

Basis of Bearing Grid North, Ohio State Plane
Coordinate System , North Zone, NAD 83
(2011). Distances shown hereon are ground
distances. To obtain grid distances multiply
distances by scale factor of 0.99995110039.



Scale 1"=50'

- Conc. Mon. Found
- ▲ 1-1/2" Rod Found
- ⊙ Pipe Found
- 5/8" Rebar Found
- ✱ 5/8" Capped Pin Found "Baker"
- Point



CERTIFICATE OF ACCURACY

I certify this survey to be correct to the best of
my knowledge.

Caleb Jerome Galbraith P.S. 8703
Date: Sept 2, 2026
Job ID: 16826

Pioneer Surveying & Services, LLC.
5434 Township Road 377
Millersburg, Ohio 44654
Phone: 330-231-0497

Email: caleb@pioneersurveyingandservices.com



Bucy Drive (49.5')

