

N.E. 1/4 Sec. 3
T8N R6W

Trustees of the
Salem Reformed
Church Vol. 45 Pg. 547

Henry A. & Edna Rober
Vol. 204 Pg. 655

I.P. set on West
side T.R. 110

163.08' I.P. F'd.

N3°38'27"E

N87°30'00"W

132.00'
German Reformed
Lutheran Church

Existing
Vol. 9 Pg. 328

Approximate
T.R. 110

part of Vol. 204
Pg. 655

28" E
119.67'
0.0628
Ac.

53°38'26"W
107.25'

107.25'

John A. & Barbara
Rober
Vol. 194 Pg. 321

50.99'
part of
Vol.
194
Pg. 321
0.1909 Ac.

587°30'00"E
132.00'

Cemetery

German Reformed
Lutheran Church
Vol. 9 Pg. 326

I.P. F'd at
S.E. corner
N.E. 1/4 Sec. 3,
and N.E.
corner S.E.
1/4 Sec. 3,
T8N, R6W
of Mec. Twp.,
Hol. Co., O.

S.E. 1/4 Sec. 3
T8N R6W
Ctr. T.R. 110

N28°07'
119.69'

N20°29'20"E
107.25'

107.25'

N87°30'

00"W


I.P. F'd.

26.71'
I.P. set

77.44'

I.P. set

132.00'



GRAPHIC SCALE IN FEET

NORTH



Known as part of Sec. 3,
T8N, R6W of Mechanic
Twp., Hol. Co., Ohio

Robert L. Kasner P.S. 5193
P.E. 28820
12117194

1873.72' N20°29'20"E

Sec. 2, T8N, R6W

MAP OFFICE COPY