



A.J. & A. MAST  
Volume 143, Page 537

ATLEE D. & ADA A. YODER  
Volume 198, Page 64

Position of Killbuck Creek &  
before being changed in 1939.  
This position is approximated  
from the stream construction  
plans.

**LEGEND**

- Stone Found
- ⊙ Railroad Spike
- Iron Pin Found
- ⊠ Post Found and Used

Surveyed Under The Supervision Of

*John V. Horst*  
John V. Horst  
Registered Surveyor No. 4522  
May, 1981



133043

REC'D. August 11, 1982  
AT 10:28 O'CLOCK a.m.  
Holmes Co. Ohio Fee: 15.00  
Recorder  
34 x 23 x 102  
Deed Vol. 217; Pg. 819.

Scale 1" = 100'

Bearing orientation is based upon observations  
taken during the overall survey of the Killbuck  
Wildlife Area.

