

R.E. BARNES 242/682

5.000 Ac. ±

KELLY W. & JO ANNE
NEAL
200/443

SE Cor.
NW QTR.
Sec. 16


J.R. & M.J. FAIR et al 260/512

Research Data: Deeds:
200/443 260/512 242/682

- = Set 3/4" x 30" rebars with aluminum caps
- ◻ = Recovered stone with "X"
- = Recovered steel pin with plastic cap

Boundary Survey
for
Marie Strouse
in
Northwest Quarter
Section 16
Range 9W, Township 8N
Richland Township
Holmes County
Ohio

Scale: 1" = 100' November 4, 1994



Bruce D. Eckelberry
R.P.S. #7103

NORTH BASED ON DEED 260/512